



No seawater access  
scrubbing water  
supply pump inlet



Pipeline 2.23  
damaged

Inlet monitor system  
fails to function



ELP

Basic 3

Manual gate valve  
1.2 fails to open

FTO


Basic 4

Manual gate valve  
1.3 fails to open

FTO

Basic 5

Electronics and  
sensing element in  
inlet monitor 1.1 fails  
to function



2/3

AOL


Basic 6


FTF


Basic 7


SPO


Basic 8












No seawater out from parallel four



Manual gate valve 2.14 fails to open

Centrifugal pump 2.15 fails to lift seawater

Manual gate valve 2.16 fails to open



FTO

ELP

FTS

UST

STD

FTO

Basic 27

Basic 28

Basic 29

Basic 30

Basic 31

Basic 32

